RTA - vehicle was passing a parked vehicle on a tight road. The wheels went off the road and the vehicle became stuck in a soft verge and required a 2 crane recovery.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**ON-HIGHWAY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**TRANSPORT & LOGISTICS / DELIVERY**	**DATE ISSUED:**	**18/09/2024 12:31:57**
SUB ACTIVITY:	**DRIVING**	**INCIDENT No:**	**04816**