

RTA - vehicle was passing a parked vehicle on a tight road. The wheels went off the road and the vehicle became stuck in a soft verge and required a 2 crane recovery.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	18/09/2024 12:31:57
SUB ACTIVITY:	DRIVING	INCIDENT No:	04816