

Fatal 3 - Graphic video shows how a mechanical engineer sustained serious injuries from fall whilst working on a conveyor repair on an HS2 site

WHAT HAPPENED

Follow this link to an HSE post on LinkedIn which shows a short video which captures the moment a mechanical engineer fell from height while working at a HS2 site.

<https://www.linkedin.com/feed/update/urn:li:activity:7220027096322949121/>

He suffered a fractured skull, hip, jaw and pelvis after landing on the concrete floor 11 metres below. The man had fallen through a gap after stair treads had been removed from a stairway.

EMC Elite Engineering Services Ltd, the man's employer, was subsequently fined over £50,000 following a HSE prosecution.

Read more about this HSE prosecution [here](#):

LEARNING POINTS / ACTIONS TAKEN

Fatal 3 - Working at Height

Review the resources that are available on this website in relation to working at height

[Fatal 3 Resources](#)

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	ACCESS & EGRESS & WORKING AT HEIGHT	DATE ISSUED:	11/11/2024 16:16:06
SUB ACTIVITY:	N/A	INCIDENT No:	04845