

# Equipment being operated without guarding

## WHAT HAPPENED

Multiple equipment across site operating without guarding.

## LEARNING POINTS / ACTIONS TAKEN

---

LOCATION:	CEMENT PLANT	ALERT STATUS:	Normal
ACTIVITY:	GUARDING AND ISOLATION	DATE ISSUED:	30/05/2025 14:08:39
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04870