

Operatives were cleaning off the cantilever belt, causing stone to fall down onto the walkway between the bottom of belt and steps.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CEMENT PLANT
ACTIVITY: MAINTENANCE & HOUSEKEEPING
SUB ACTIVITY: CONVEYORS

ALERT STATUS: Normal
DATE ISSUED: 06/06/2025 12:52:46
INCIDENT No: 04903