Operatives were cleaning off the cantilever belt, causing stone to fall down onto the walkway between the bottom of belt and steps.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CEMENT PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**MAINTENANCE & HOUSEKEEPING**	**DATE ISSUED:**	**06/06/2025 12:52:46**
SUB ACTIVITY:	**CONVEYORS**	**INCIDENT No:**	**04903**