

**Rock trap overwhelmed when approximately 20t of sand and gravel flowed on to the haul road. Unusually wet conditions - material had been deliberately dropped into the rock trap area.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>QUARRY</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>PRODUCTION AND PROCESSING</b>	<b>DATE ISSUED:</b>	<b>09/06/2025 19:08:24</b>
<b>SUB ACTIVITY:</b>	<b>AGGREGATE PROCESSING</b>	<b>INCIDENT No:</b>	<b>04909</b>