

# Historic detonator miss fire identified in quarry

## WHAT HAPPENED

Historic misfire identified by the presence of a single 30cm length of red detonator cord visible at height in a previously blasted rock face. It is believed that recent rains had uncovered the red detonator cord in the rock face.

## LEARNING POINTS / ACTIONS TAKEN

---

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	QUARRYING AND FACE ACTIVITY	DATE ISSUED:	09/06/2025 19:13:14
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04910