

BEST PRACTICE

LOCATION:	Manufacturing - minerals	ARTICLE YEAR	2021
ACTIVITY:	Access & Egress & Working at Height	COMPANY:	Imerys Aluminates Ltd
SUB ACTIVITY:	N/A	COMPANY LOCATION:	West Thurrock
BEST PRACTICE No:	BP2090	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE



Truck gantry for safe working at height

ARTICLE

Entry 21033 Winner Fatal 3

In 2020, at Imerys Aluminates' West Thurrock site there was an incident where migrants were discovered inside one of their raw material tankers arriving from continental Europe. The police were called and thankfully, all were safe and well.

This event highlighted the need to inspect all incoming tankers for illegal migrants before pumping off. It also highlighted that while there was a safe system for accessing tankers and opening ports at the loading stations, it relied on drivers using their single handrail, this still exposed them to a work at height risk.

To mitigate this risk, a truck gantry was installed.

Please [click here](#) for more information or on additional pdf.

ARTICLE IMAGES

Click image to enlarge



Click image to enlarge

