BEST PRACTICE

LOCATION:	**Quarry**	**ARTICLE YEAR**	**2006**
ACTIVITY:	**Transport & Logistics / Delivery**	**COMPANY:**	**Aggregate Industries**
SUB ACTIVITY:	**Mobile Plant**	**COMPANY LOCATION:**	**Bardon Aggregates, Lancashire**
BEST PRACTICE No:	**BP364**	**COMPANY TEL:**	**07802 276 158**
COUNTRY OF ORIGIN:	**United Kingdom**		

TITLE


CCTV cameras reduce tipper overturns

ARTICLE

One of the difficulties associated with the transportation and tipping of heavy loads is the overturning of articulated tippers. In an attempt to prevent overturns, Bardon Aggregates installed CCTV cameras in the front-inside of the vehicle body. The image is then relayed to a monitor in the cab. The driver can now observe, visually, the loading and discharging operations from the safety of the vehicle cab, assessing if there is likely to be any danger of the lorry tipping.

ARTICLE IMAGES

Click image to enlarge



vehicle tipping

Click image to enlarge



cctv image