

## INCIDENT ALERT

**INCIDENT TIME:** Out of hours weekday      **DATE:** 14/02/2014 15:21:08  
**COUNTY:** Kinross-shire      **LOCATION:** Rural  
**INCIDENT No:** 00029

### Electric cable theft

#### INCIDENT DETAILS

Steel container broken into housing electrical switch gear, 4 core electric cables cut, site telehandler then used to pull the cable out of the ground and remove to field opposite the site entrance, bursting through boundary fence with on site telehandler. 60mt in total stolen. Telehandler was left in field undamaged.

#### POLICE REACTION

DNA samples taken from telehandler.

#### HEALTH AND SAFETY IMPLICATIONS

Site is generator driven, so no threat to safety.

#### LEARNING POINTS

Additional security measures put in place.

#### IMAGES