

# Tytherington Quarry Mobile Plant Parking Area



Aerial photo showing mobile area layout and pedestrian walkways.



# New walkway from the canteen to the parking area



Segregated walkways, additional lighting and flags/buggy whips on dividers



# Photographs showing parking area in hours of darkness



Previous issues of ADTS not having enough parking room, and parking within stock areas and on traffic routes.



Previous problem.. A significant near hit when a shovel loading the 2/6mm pile reversed into a parked dumper.



Before:



Original parking area 1  
– Asphalt's  
RAP area

Original parking area 2  
– stockyard  
and active  
haul road.

Original parking area 3

Pedestrian  
Walkways  
(yellow)

Canteen

Workshop  
and LV source

2/6mm pile



# After:

New and improved  
Pedestrian  
Walkways (yellow)

Canteen



All mobile  
plant parking  
in the same  
area. Access  
via walkways.

Better access  
for mobile  
plant and  
pedestrians to  
workshop.

Armco barrier  
to segregate  
area