

BEST PRACTICE

LOCATION: Asphalt/Coating plant **ARTICLE YEAR:** 2005
ACTIVITY: Production and Processing **COMPANY:** Bardon Aggregates
SUB ACTIVITY: Asphalt & coated stone **COMPANY LOCATION:** Hulands Asphalt Plant, County Durham
BEST PRACTICE No: BP155 **COMPANY TEL:** 01833 628320

TITLE

Alarm system for drench showers

ARTICLE

A new alarm system activated by the drench showers at Bardon Aggregates means that the workforce is aware of an accident immediately and help is at hand for the injured person. The audio / visual alarms are situated in the laboratory, the mixer cabin and in an elevated position above the bitumen tanks. Toolbox talks have been carried out with all personnel to train them on procedures following a bitumen incident.

ARTICLE IMAGES



Alarm system for drench showers