## **BEST PRACTICE**

**LOCATION**: Quarry **ARTICLE YEAR**: 2002

ACTIVITY: Manual handling and storage COMPANY: CEMEX UK

SUB ACTIVITY: N/A COMPANY LOCATION: Raynes Quarry, Clwyd

**BEST PRACTICE No:** BP169 **COMPANY TEL:** 01492 517378

## Manual handling improvements programme

## **ARTICI F**

Recognising the hazards that go with manual handling, this quarry near Colwyn Bay in North Wales has instigated a raft of measures that include:

L purchase of vacuum cleaning system to avoid spadework in restricted spaces in crushing plant

L use of light, wheeled welding screen

L modified engine hoist to remove electric motors from store where there is no fork-lift access

L installed travelling gantry to handle 205-litre oil drums

L charging primary crusher bearing with grease using pumped system.

ARTICLE IMAGES		