

BEST PRACTICE

LOCATION: **ARTICLE YEAR:** 2008
ACTIVITY: Access & Egress & Working at Height **COMPANY:** Aggregate Industries
SUB ACTIVITY: N/A **COMPANY LOCATION:** Ghyll Scaur Quarry
BEST PRACTICE No: BP573 **COMPANY TEL:** 01229 770580

TITLE

Elevated walkway for safer pedestrian passage

ARTICLE

There are space constraints at this plant which create a danger for pedestrians as their paths cross that of mobile plant. The issue was resolved by the construction of a designated, elevated pedestrian walkway.

The walkway runs from the office block to a parking bay, large enough to accommodate the mobile plant fleet, creating a safer area for pedestrians.

ARTICLE IMAGES

