

BEST PRACTICE

LOCATION:
ACTIVITY: Production and Processing
SUB ACTIVITY: Aggregate processing
BEST PRACTICE No: BP663

ARTICLE YEAR: 2009
COMPANY: Aggregate Industries
COMPANY LOCATION: Colemans Quarry, Somerset
COMPANY TEL: 01373 836130

TITLE

Asphalt plant loading display

ARTICLE

A television monitor has been installed at Colemans Quarry to ensure that loading at the asphalt plant is managed safely.

Encased in a specialised weatherproof box, the monitor is located within a guarded-off area to the front of the plant giving lorry drivers a perfect view of the screen.

The information displayed includes tonnage of load, material being loaded and also has a timer to count down to when the next batch will be dropped from the mixer.

The system stops drivers pulling out from under the plant prematurely, increasing driver safety.

ARTICLE IMAGES