

BEST PRACTICE

LOCATION:

ARTICLE YEAR: 2009

ACTIVITY: Production and Processing

COMPANY: Aggregate Industries

SUB ACTIVITY: Aggregate processing

COMPANY LOCATION: Peterborough Asphalt Plant, Peterborough

BEST PRACTICE No: BP665

COMPANY TEL: 07740 934550

TITLE

Skip track safety catch

ARTICLE

A potential hazard was identified at Peterborough Asphalt Plant. When the skip track was lifted to provide access under the mixer, it was only supported by the chain hoist and had no back-up safety catch.

A safety catch was fabricated and installed to act as a back-up should the hoist fail, preventing possible serious injuries.

ARTICLE IMAGES

