

BEST PRACTICE

LOCATION: **ARTICLE YEAR:** 2009
ACTIVITY: Access & Egress & Working at Height **COMPANY:** Aggregate Industries
SUB ACTIVITY: N/A **COMPANY LOCATION:** Bardon Hill, Leicestershire
BEST PRACTICE No: BP669 **COMPANY TEL:** 07740 934436

TITLE

Manual handling zip line

ARTICLE

The Standard Havens dryer drum located at Bardon Hill is a considerable length with lifters and other heavy parts located internally.

Parts such as 30kg lifters had to be carried by hand whilst negotiating various trip hazards within the dryer.

To reduce the associated risks, a zip line arrangement was fitted inside the dryer to allow the lifters to be hooked on and moved into position. This has greatly reduced the manual handling risk.

ARTICLE IMAGES

