INCIDENT ALERT

LOCATION:	Construction/delivery site	ALERT STATUS:	Normal
ACTIVITY:	Access & Egress & Working at Height	DATE ISSUED:	15/02/10
SUB ACTIVITY:	N/A	INCIDENT No:	00252
TIT! E			
Attaching Lanyard to Fall Arrest Harness			
ACCIDENT / INCIDENT DETAILS			
Safety Alert received from Build Safe United Arab Emirates:			
A contractor caught his leg in the lanyard of his harness. He fell and sustained a cut that required six stitches.			
(see additional pdf)			
ACCIDENT / INCIDENT IMAGES			
I EARNING BOIN	TS / ACTIONS TAKEN		
Use a shorter lany			
Use a lanyard with a retractable line			
Attach the lanyard such that it does not loop below the knee			
A method should be selected which takes into consideration the type of work being done and the conditions at the work site.			
LEARNING POINTS / ACTIONS IMAGES			