

INCIDENT ALERT

LOCATION: Quarry
ACTIVITY: Transport / Delivery
SUB ACTIVITY: Mobile Plant

ALERT STATUS: Normal
DATE ISSUED: 12/05/10
INCIDENT No: 00261

TITLE

HSE Alert 4x4 Rollover

ACCIDENT / INCIDENT DETAILS

A contractor was killed when a 4x4 road vehicle overturned on a quarry haulroad.

Although the operator was thrown clear during the incident, the roof of the vehicle collapsed.

Details of the HSE safety alert can be found at
<http://www.hse.gov.uk/safetybulletins/rolloverrisk.htm>

ACCIDENT / INCIDENT IMAGES

LEARNING POINTS / ACTIONS TAKEN

Review arrangements to ensure that:

The risk of vehicle rollover has been adequately assessed.

Where a risk exists, any vehicle exposed to that risk has adequate protection for the operator in the event of an overturn.

If necessary, vehicles should be fitted with additional rollover protection such as rollover cages.

Seat belts should be fitted and worn.

LEARNING POINTS / ACTIONS IMAGES