- Wearing a seat belt and not carrying any loose equipment in the cab will help to prevent injuries

- Journey Planning should be undertaken for all deliveries, and could identify where an alternative / safer route is necessary. In this case a movement order had been applied for but had not been issued. The Police had instructed the crane provider to use an alternative route but this had not been communicated to the driver.

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	08/08/2017 10:43:48
SUB ACTIVITY:	ON-HIGHWAY	INCIDENT No:	01463