Driver Removed from Site

WHAT HAPPENED

A driver delivered a load of aggregate to the works and tipped into a ground bin. After tipping he observed some of the load had frozen to the body. He drove the lorry to a quiet part of the site, tipped the body and then entered via the tailgate to clean off the residue.

He was observed by a supervisor who via a safety conversation; stopped the driver and requested he explain his actions. The driver was spoken to about the unsafe act and then removed from site.



Tipped Truck

LEARNING POINTS / ACTIONS TAKEN

Remember; never pass an unsafe act or condition without taking action.

The site is to review tipping procedures and make arrangements to safely allow access and egress to tipper bodies should the need arise.

LOCATION:	**CONCRETE PRODUCTS PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**TRANSPORT & LOGISTICS / DELIVERY**	**DATE ISSUED:**	**09/02/2012**
SUB ACTIVITY:	**MOBILE PLANT**	**INCIDENT No:**	**00324**