

**Isolation Breach - Operative had followed LOTOTO and was cleaning in area 1. The operative was able to pass through from one lock-off zone to Area 2. When entering the new zone, the operative activated a sensor which started the plant (Precast )**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>CONCRETE PRODUCTS PLANT</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>03/09/2024 17:11:44</b>
<b>SUB ACTIVITY:</b>	<b>CONVEYORS</b>	<b>INCIDENT No:</b>	<b>03743</b>