

**Isolation Breach - Plant operator attempting to clear stone blockage from jaw crusher climbed over stuck rock with equipment still on with the engine running. The conveyor observed to be running, with the crusher jaws off.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

**LOCATION:** QUARRY  
**ACTIVITY:** PRODUCTION AND PROCESSING  
**SUB ACTIVITY:** AGGREGATE PROCESSING

**ALERT STATUS:** High Potential  
**DATE ISSUED:** 03/09/2024 17:38:36  
**INCIDENT No:** 03747