

Articulated delivery vehicle rolled both tractor unit and trailer when tipping a load at a customer's site.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	11/09/2024 18:35:30
SUB ACTIVITY:	DELIVERING AGGREGATES	INCIDENT No:	03764