

Person seen working alone on a roof with no Permit to Work, no fall protection, lack of PPE or management of the activity.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: READYMIX OR MORTAR PLANT
ACTIVITY: ACCESS & EGRESS & WORKING AT HEIGHT
SUB ACTIVITY: N/A

ALERT STATUS: Normal
DATE ISSUED: 11/09/2024 19:40:42
INCIDENT No: 03777