

Person seen outside of the MEWP he was using, not attached to any anchor point standing on top of an open water tank whilst proceeding to carry out installation of the cladding.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	ACCESS & EGRESS & WORKING AT HEIGHT	DATE ISSUED:	11/09/2024 19:42:57
SUB ACTIVITY:	N/A	INCIDENT No:	03778