

Loading - Driver exposed to risk of fall from height after striking his head on scaffold pole while on loading gantry

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

---

LOCATION:	LIME & SLAG PLANTS	ALERT STATUS:	Normal
ACTIVITY:	ACCESS & EGRESS & WORKING AT HEIGHT	DATE ISSUED:	12/09/2024 12:45:38
SUB ACTIVITY:	N/A	INCIDENT No:	03779