

Lifting - A piece of a concrete unit broke away whilst being stacked on another and dropped to the ground, striking operatives hard hat on its descent to the floor.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: LOADING AND UNLOADING
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal
DATE ISSUED: 13/09/2024 12:17:42
INCIDENT No: 03800