Fatal 3 - Graphic video shows how a mechanical engineer sustained serious injuries from fall whilst working on a conveyor repair on an HS2 site

WHAT HAPPENED

Follow this link to an HSE post on Linkedin which shows a short video which captures the moment a mechanical engineer fell from height while working at a HS2 site.

https://www.linkedin.com/feed/update/urn:li:activity:7220027096322949121/

He suffered a fractured skull, hip, jaw and pelvis after landing on the concrete floor 11 metres below. The man had fallen through a gap after stair treads had been removed from a stairway.

EMC Elite Engineering Services Ltd, the man's employer, was subsequently fined over £50,000 following a HSE prosecution.

Read more about this HSE prosecution here:

LEARNING POINTS / ACTIONS TAKEN

Fatal 3 - Working at Height

Review the resources that are available on this website in relation to working at height

Fatal 3 Resources

LOCATION:	**CONSTRUCTION/DELIVERY SITE**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**ACCESS & EGRESS & WORKING AT HEIGHT**	**DATE ISSUED:**	**11/11/2024 16:16:06**
SUB ACTIVITY:	**N/A**	**INCIDENT No:**	**04845**