

TRANSPORT - Low loader rolled backwards and collided into planer

WHAT HAPPENED

A low loader rolled backwards when the driver released the parking brake and attempted to select 1st gear to move the vehicle. In doing so the trailer rolled into a stationary planer. The planer operator was on the working platform but was unharmed

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	06/06/2025 12:46:20
SUB ACTIVITY:	BRAKES AND RUNAWAYS	INCIDENT No:	04901