

Rock trap overwhelmed when approximately 20t of sand and gravel flowed on to the haul road. Unusually wet conditions - material had been deliberately dropped into the rock trap area.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	09/06/2025 19:08:24
SUB ACTIVITY:	AGGREGATE PROCESSING	INCIDENT No:	04909