

TRANSPORT - Spillage of hydraulic oil creates hazard from road users

WHAT HAPPENED

Artic vehicle delivering sand to site deposited hydraulic oil on the highway leading to the entrance to site. Cyclist slipped on oil at the junction with the main road. Minor cuts and bruises. Police were informed who attended the scene, called in the fire service who have closed the road to clear the spill that had worsened due to traffic..

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	10/06/2025 11:38:52
SUB ACTIVITY:	DELIVERING AGGREGATES	INCIDENT No:	04918