

# Fatal 5 - Skip full of concrete falls during craning operation

## WHAT HAPPENED

A recent incident at a concrete products site resulted in a skip full of concrete falling from height, whilst being craned into position. No person was injured as a result of the incident, but it does reinforce the need to ensure we have no persons operating close to or under any suspended loads. Please see incident 04928 for more information.

## LEARNING POINTS / ACTIONS TAKEN

---

LOCATION:	CONCRETE PRODUCTS PLANT
ACTIVITY:	LIFTING
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE

ALERT STATUS:	Normal
DATE ISSUED:	18/09/2025 11:30:58
INCIDENT No:	04929