


## BEST PRACTICE

LOCATION: Brickworks  
ACTIVITY: Maintenance & Housekeeping  
SUB ACTIVITY: N/A  
BEST PRACTICE No: BP2086  
COUNTRY OF ORIGIN:

ARTICLE YEAR: 2021  
COMPANY: Mansfield Sand Co Ltd  
COMPANY LOCATION: Brick Division  
COMPANY TEL: 0000

TITLE	
<b>Safe kiln access and inspection project</b>	
<b>ARTICLE</b>	
<p><b>Entry 21003    Winner    Fatal 1,3 and 5</b></p> <p>The brickworks at Mansfield Sand have a large curing chamber for the bricks consisting of racking configured into 9 lanes, each containing room for 30 stacks of pallets, each stack is 19 pallets high. As a result, this is deemed a critical structure and must be maintained in good condition to remain structurally sound.</p> <p>Following an incident where someone fell and was injured, Mansfield recognised that it was necessary to improve both pedestrian and machine access to the kilns. At the same time, a more frequent inspection policy was introduced making the provision of good access even more critical.</p> <p>Please <a href="#">click here</a> for more information or on additional pdf</p>	
<b>ARTICLE IMAGES</b>	