BEST PRACTICE

LOCATION:	**Brickworks**	**ARTICLE YEAR**	**2021**
ACTIVITY:	**Maintenance & Housekeeping**	**COMPANY:**	**Mansfield Sand Co Ltd**
SUB ACTIVITY:	**N/A**	**COMPANY LOCATION:**	**Brick Division**
BEST PRACTICE No:	**BP2086**	**COMPANY TEL:**	**0000**
COUNTRY OF ORIGIN:			

TITLE

Safe kiln access and inspection project

ARTICLE

Entry 21003 Winner Fatal 1,3 and 5

The brickworks at Mansfield Sand have a large curing chamber for the bricks consisting of racking configured into 9 lanes, each containing room for 30 stacks of pallets, each stack is 19 pallets high. As a result, this is deemed a critical structure and must be maintained in good condition to remain structurally sound.

Following an incident where someone fell and was injured, Mansfield recognised that it was necessary to improve both pedestrian and machine access to the kilns. At the same time, a more frequent inspection policy was introduced making the provision of good access even more critical.

Please **click here** for more information or on additional pdf

ARTICLE IMAGES