BEST PRACTICE

LOCATION:	**Quarry**	**ARTICLE YEAR**	**2006**
ACTIVITY:	**Maintenance & Housekeeping**	**COMPANY:**	**Aggregate Industries**
SUB ACTIVITY:	**N/A**	**COMPANY LOCATION:**	**Holme Park Quarry, Lancashire**
BEST PRACTICE No:	**BP318**	**COMPANY TEL:**	**01524 781441**
COUNTRY OF ORIGIN:	**United Kingdom**		

TITLE
Crusher access
ARTICLE
Maintenance, repairs and inspection of the quarry's Mansfield crushers, created difficulties regarding manual handling, the lifting operations involving a crane, added to which, access for inspection, repairs and adjustments was poor. It was decided to create a hydraulically operated door and hinged front panel to remedy these health and safety issues. This also included a mechanism for retaining the top hinged door whilst open. This system was then applied to the remaining crushers.
ARTICLE IMAGES