

## BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2006
ACTIVITY:	Production and Processing	COMPANY:	CEMEX
SUB ACTIVITY:	Aggregate processing	COMPANY LOCATION:	Dove Holes Quarry, Derbyshire
BEST PRACTICE No:	BP353	COMPANY TEL:	01298 77531
COUNTRY OF ORIGIN:	United Kingdom		

### TITLE

Sample point chute

### ARTICLE

The mortar plant sand product must be sampled regularly but the only place to do so was at the input point to the silo which was 40 metres high. This was deemed unacceptable, so the fitter came up with an idea to make a sample point into the chute at the bottom of the elevator. The system took a sample across the full product flow and reduced the need to climb to the top of the silo and return with a sample load.

### ARTICLE IMAGES