BEST PRACTICE

LOCATION:	**Quarry**	**ARTICLE YEAR**	**2006**
ACTIVITY:	**Access & Egress & Working at Height**	**COMPANY:**	**CEMEX**
SUB ACTIVITY:	**N/A**	**COMPANY LOCATION:**	**Hartley Quarry and Coating Plant, Cumbria**
BEST PRACTICE No:	**BP405**	**COMPANY TEL:**	**017683 71479**
COUNTRY OF ORIGIN:	**United Kingdom**		

TITLE
Hinged ladder
ARTICLE
Occasionally, this coating plant requires access to view the condition and contents of the cold feed aggregate bins and the clearance of material build-up from the corners of the bin. The old steps and ladder were repeatedly damaged by the loading shovel feeding the bin and so were replaced with a hinged ladder, which can be swung out of the working area.
ARTICLE IMAGES